



Cleaning and Maintenance

Ampelite Natural Lighting sheets (PVC Polycarbonate and Fiberglass) require a minimum level of maintenance to guarantee their best possible performance.

This maintenance should include, but not be limited to, keeping surfaces clean and free from prolonged contact with debris and moisture. The sheets should be washed at least every 12 months with a soft brush and a mild household detergent, like dish washing liquid to prevent and remove any dirt build up.

Do not use spray-on moss and mould type cleaners, or other cleaners that are left on the surface over time to work. These types of cleaners can damage the surface coatings applied to Ampelite Natural Lighting sheeting, causing early failure.

It is important that Ampelite Natural Lighting sheets are thoroughly rinsed after cleaning to ensure no residue is left on the sheeting.

Avoid chemicals, paint, adhesives and other synthetic materials as this can also cause damage.

Washers and fasteners should be monitored regularly for signs of deterioration. This can help prevent any leak points or staining of the sheeting.

Do not wash with any high-pressure appliance, such as water blasters, as these can also damage the sheeting.

For any further contact Ampelite on 0800 267 354